03500.017608. JUL 2 6 2006 W

Cole PATENT

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	
HIROKI SUE, et al.	Examiner: R. Patel )
Appl. No.: 10/633,037	: Group Art Unit: 2838
Filed: August 4, 2003	Central
For: POWER SUPPLY CONTROL APPARATUS	or con 3 1 200
U.S. Patent No.: 6,952,357 B2	Cito
Issued: October 4, 2005	) : July 25, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

> REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

67/27/2696 SDENBUBI 68689186 6952357

61 FC:1811 189.69 OP

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Ohn D. Magdiyan Attorney for Patentees Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA\_MAIN 116530v1

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,952,357 B2

**DATED** 

October 4, 2005

INVENTOR(S) :

Sue, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **COVER PAGE:**

(57) **ABSTRACT**, line 8, "lowered" should read -- lowered, --.

## COLUMN 4:

Line 1, "Ti," should read -- T1, --.

#### COLUMN 5:

Line 5, "obtain" should read -- obtained --; and Line 56, "(a" should read -- (an --.

## COLUMN 9:

Line 6, "again the" should read -- again of the --.

#### COLUMN 10:

Line 1, "again the" should read -- again of the --.

CA\_MAIN 116528v1

**MAILING ADDRESS OF SENDER:** 

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

**PATENT NO. 6,952,357 B2** 

No. of add'l. copies @ 30¢ per page





## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,952,357 B2

DATED

October 4, 2005

INVENTOR(S) :

Sue, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **COVER PAGE:**

(57) **ABSTRACT**, line 8, "lowered" should read -- lowered, --.

## COLUMN 4:

Line 1, "Ti," should read -- T1, --.

## COLUMN 5:

Line 5, "obtain" should read -- obtained --; and Line 56, "(a" should read -- (an --.

## COLUMN 9:

Line 6, "again the" should read -- again of the --.

#### COLUMN 10:

Line 1, "again the" should read -- again of the --.

CA\_MAIN 116528v1

MAILING ADDRESS OF SENDER:

PATENT NO. 6,952,357 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

MO